

1/9




FIG. 1

2/9




FIG. 2

3/9





FIG. 3



5/9




FIG. 5




FIG. 6

6/9




FIG. 7

510	502	512	514	516	518	520	522
WELD	DESCRIPTION	EXAM TYPE	LAST INSPECTION	CRITERIA MET?	INDICATIONS	COMMENTS	
CRGT-2, G-08	CRD GUIDE TUBE BODY-TO-SLEEVE WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-2, H-07	CRD GUIDE TUBE BODY-TO-SLEEVE WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, F-08	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, G-06	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, G-07	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, G-08	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, G-08	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, H-06	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, H-07	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, H-08	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, H-09	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, J-07	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	
CRGT-3, J-08	CRD GUIDE TUBE BODY WELD	VT-3/4	AUG 1995	Y	N	DETAILS	

EXAMINED APPROXIMATELY 50% OF CIRCUMFERENCE (EAST SIDE) DUE TO INTERFERENCES

FIG. 8

8/9

HISTORICAL EXAM

MIDWEST ROG

LAST INSPECTION RANGE: JAN 1990 JAN 2010 DRESDEN 2

COMPONENTS: ALL

CRITERIA MET?: ALL

INDICATIONS: ALL

OK BACK

JAN 05, 2001

ALL	628
CORE SPRAY	630
CP STIFFENER BEAMS	632
CONTROL ROD DRIVE HOUSING	634
CONTROL ROD GUIDE TUBES	636
PIPE BRACKET	638
CORE SPRAY SPARGER	640
FEED WATER SPARGER	642
INCORE HOUSING	644
INCORE GUIDE TUBE	646
SRM/IRM	648
JET PUMP	650
MOISTURE SEPARATOR	652
RPV INTERIOR	654
SHROUD	656
CDR STUB TUBE	658
STEAM DRYER	660
TG ALIGN PIN	662

FIG. 9

9/9

710 COMPONENT: CORE SPRAY 702 712 714 716 718 720 722 724

WELD	DESCRIPTION	EXAM TYPE	LAST INSPECTION	CRITERIA MET?	INDICATIONS	NEXT REQUIRED EXAM	COMMENTS
1P3	HORIZONTAL PIPE TO JUNCTION BOX LOOP A @ 5° AZIMUTH	UT	MAR-1999	Y	N	MAR-2002	DETAILS
1P4A	HORIZONTAL PIPE TO ELBOW LOOP A @ 5° AZIMUTH ELBOW TO PIPE	UT	MAR-1998	Y	N	MAR-2006	DETAILS
1P4B	DOWNCOMER LOOP A @ 80° DOWNCOMER	UT	MAR-1998	Y	N	MAR-2006	DETAILS
1P4C	LOWER DOWNCOMER TO ELBOW WELD LOOP A @ 80° AZIMUTH	UT	MAR-1998	Y	N	MAR-2006	DETAILS
1P4D	LOWER ELBOW TO SHROUD PIPE WELD LOOP A @ 80° AZIMUTH	EVT-1	OCT-1999	Y	N	OCT-2007	DETAILS
1P5	SLIDING SLEEVE TO UPPER DOWNCOMER LOOP A @ 80° DOWNCOMER	EVT-1	MAR-1998	Y	N	MAR-2000	DETAILS
1P6	SLIDING SLEEVE WELD TO OUTER SLEEVE LOOP A @ 80° DOWNCOMER	UT	MAR-1998	Y	N	MAR-2002	DETAILS
1P7	OUTER SLEEVE TO LOWER DOWNCOMER WELD LOOP A @ 80° DOWNCOMER	UT	MAR-1998	Y	N	MAR-2002	DETAILS
1P8A	COLLAR WELD TO SHROUD PIPE LOOP A @ 80° DOWNCOMER	EVT-1	OCT-1999	Y	N	OCT-2001	DETAILS

UT OF CREVICED OF TEE-BOX TO PIPE WELD WITH NO INDICATIONS (BWRVIP-18)

FIG. 10

726